

Příloha 1 Tabulka konstant potřebných pro výpočty

Rozsah podskupiny	Součinitelé pro regulační meze							Dělitelé pro odhad σ	
	A ₂	D ₃	D ₄	A ₃	B ₃	B ₄	E ₂	d ₂	c ₄
2	1,880	---	3,267	2,659	---	3,267	2,660	1,128	0,7979
3	1,023	---	2,574	1,954	---	2,568	1,772	1,693	0,8862
4	0,729	---	2,282	1,628	---	2,266	1,457	2,059	0,9213
5	0,577	---	2,114	1,427	---	2,089	1,290	2,326	0,9400
6	0,483	---	2,004	1,287	0,030	1,970	1,184	2,534	0,9515
7	0,419	0,076	1,924	1,182	0,118	1,882	1,109	2,704	0,9594
8	0,373	0,136	1,864	1,099	0,185	1,815	1,054	2,847	0,9650
9	0,367	0,184	1,816	1,032	0,239	1,761	1,010	2,970	0,9693
10	0,308	0,223	1,777	0,975	0,284	1,716	0,975	3,078	0,9727

Zdroj: (Česká společnost pro jakost, 2006)