

Appendix

Appendix 1 Price list by type of work in a car service

№	TYPES OF WORK	UNITS; LABOUR HOURS	LABOUR-HOUR COST; UAH	SERVICE COST; UAH
1.	Replacing the brake pads (front)	1,4	500	700
2.	Changing the engine oil	0,8	500	400
3.	Replacing the ball joint	1,6	500	800
4.	Replacing brake discs	2,6	500	1300
5.	Replacing the air filter	0,4	500	200
6.	Replacing steering tips	1,8	500	900
7.	Replacing the silent blocks of the front arm	1,2-3,6	500	600-1800
8.	Replacing the front crankshaft oil seal	2,4-3,9	500	1200-1950
9.	Replacing the pump	3,2-5,8	500	1600-2900
10.	Replacing the cooling pipes	1,1-4,8	500	450-2400
11.	Replacing the cooling radiator	2,9-5,7	500	1450-2850
12.	Replacing the front shock absorbers	3,5-6,3	500	1750-3150
13.	Replacing the alternator belt with tension rollers	2,4-6,1	500	1200-3050
14.	Replacing the valve cover gasket	1,8-3,2	500	900-1600
15.	Replacing the clutch	6,8-11,4	500	3400-5700
16.	Gearbox repair	7,9-17,5	500	3950-8750
17.	Replacing the hub bearing (front)	2,4-5,7	500	1200-2850
18.	Replacing rear suspension silent blocks	2,4-9,6	500	1200-4800

19.	Replacing the low beam bulb	0,6-1,9	500	300-950
20.	Removal - installation of injectors (petrol engine)	2,0-5,9	500	1000-2950
21.	Cleaning nozzles at the stand	2,0-4,0	500	1000-2000
22.	Cleaning injectors (petrol, diesel) on the engine	4,2-10,5	500	2100-5250
23.	Removal - installation of the engine	11,5-27,8	500	5750-13900
24.	Engine repair	12,0-24,5	500	6000-12250
25.	Removal - installation of an automatic transmission	5,5-8,7	500	2750-4350
26.	Repair of an automatic transmission	10,5-30,0	500	5250-15000
27.	Replacing the fuel pump on a gasoline engine	5,5-12,5	500	2750-6250
28.	Replacing the high-pressure fuel pump on a diesel engine	10,5-25,0	500	5250-12500
29.	Replacing the fuel filter	1,3- 4,8	500	650-2400
30.	Alarm installation	6,0-15,5	500	3000-7750
31.	Installation of speaker systems	3,5-20,0	500	1750-10000
32.	Glass tinting	2,5-10,4	500	1250-5200
33.	Installation of air conditioner	12,0-35,0	500	6000-17500
34.	Installation of hatches	10,5-17,0	500	5250-8500
35.	Installation of autonomous heaters	12,5-32,5	500	6250-16250


Source: Author's creation

Appendix 2 Volume of services provided

Name	Units; Labour-hour								
	First year			Second year			Third year		
	day	month	year	day	month	year	day	month	year
First master (locksmith work)	5	120	1440	8	189	2268	7	158	1896
Second master (Locksmith and electrical work)	6	143	1710	11	261	3132	9	217	2604
Total:	11	263	3150	19	450	5400	16	375	4500

Source: Author's creation

Appendix 3 The layout of the premises



Source: Author's creation